


Excel Compressor Engineering Ltd

Airend Refurbishment Facility



Consider this

- All Manufacturers recommend overhaul of their Airend Units at between 20,000 and 24,000 running hours
- **Why?**
- If your Airend fails, either through seizure or partial seizure there is an 80% plus chance it will need to be replaced.
- If your Airend has "clocked" around 20,000 hours or is starting to become noisy, there is a 95%+ chance it can be overhauled.
- **"I might as well wait until it seizes and do it then!"**
- The average saving having your Airend overhauled against replacement is usually around 60%
- Even small Airend's (7.5 & 11 kW) can jump from approx. £850.00 to over £2,000.00 if left until failure
- Be smart, save energy & money - Ask for a price to Overhaul your Airend Today

What is involved?

- Unit will be removed from Compressor and site made ready for re-installation
- Unit stripped and inspected, commencement of rebuild including the installation of new bearings, gaskets and seals
- Where necessary, any re-metal and grinding of Shafts and Rotors as required, repair of front and rear housing metalwork. Use of OEM Bearings & Balancing of Rotors
- In the unusual event that after inspection our service department determines the Airend is beyond economical repair, we will contact you and explain why - detailing any other options available
- Re-installation of Airend into compressor, full commissioning and test procedure



For further information contact:

Service Department - 0161 366 1886 or
Mike Irvine - 07866 388 840 or
Steve Eyres - 07973 417 225
e-mail - info@excelcompressors.co.uk